



Estimated Quote

From:

HandyManSouthampton

Southampton

Contract no.: 07300300155

E: info@wefix24.co.uk

www.wefix24.co.uk

Estimated Quote Number HMS116

Estimated Quote Date 06/03/2023

Valid Until 08/04/2023

Total £1,805.00

To:

| Hrs/Qty | Service | Rate/Price | Sub Total |
|---------|--|------------|-----------|
| 1 | Shutter doesn't work automatically; site staff are having to use a pulling rope to operate the shutter. Shutter dimensions 4m (W) x 6m (H). diagnostic charges apply (will price after looking) | £150.00 | £150.00 |
| 0 | Manual entrance door to locker area has been damaged from outside causing it to not close properly. Door dimensions: 2300mm (H) x 1180mm (W) (will price after looking) | £0.00 | £0.00 |
| 1 | Damaged wall in Locker/bike store area 700mm x 500mm (plasterboard) Prepare and repaint whole wall 6m x 2.3m | £475.00 | £475.00 |
| 1 | repair hole in plasterboard 500mm x 200mm Paint repaired area only | £100.00 | £100.00 |
| 1 | (diagnostic charges only)Air Conditioning Unit: Internal & External Error code showing on control panel. Both internal and external not working due to this issue. External A/C dimensions 9700mm (H) x 9700mm (W). | £200.00 | £200.00 |
| 1 | Cleaners' cupboard: • Repair holes in plasterboard, prepare and repaint walls, refix mop holder (currently onsite) • Room dimensions 1.2m x 2.4m x 2.4m (H) • 2.88x2 = 5.7*x2= 17=435 | £600.00 | £600.00 |

Thanks for choosing [HandyMan Southampton](http://HandyManSouthampton) | info@wefix24.co.uk



Estimated Quote

| Hrs/Qty | Service | Rate/Price | Sub Total |
|--------------|---|------------|------------------|
| 2 | Supply and install coat hooks on inside toilet doors (1 each in male and female) | £100.00 | £200.00 |
| 1 | Hot water pressure is very low in all sinks on the premises. diagnosis charges | £80.00 | £80.00 |
| Sub Total | | | £1,805.00 |
| Tax | | | £0.00 |
| Total | | | £1,805.00 |

<https://wefix24.co.uk/terms-conditions/>