



Estimated Quote

From:

[HandyManSouthampton](#)

Southampton

Contract no.: 07300300155

E: info@wefix24.co.uk

www.wefix24.co.uk

Estimated Quote

HMS116

Number

Estimated Quote Date 06/03/2023

Valid Until 08/04/2023

Total £1,805.00

To:

Hrs/Qty	Service	Rate/Price	Sub Total
1	Shutter doesn't work automatically; site staff are having to use a pulling rope to operate the shutter. Shutter dimensions 4m (W) x 6m (H). diagnostic charges apply (will price after looking)	£150.00	£150.00
0	Manual entrance door to locker area has been damaged from outside causing it to not close properly. Door dimensions: 2300mm (H) x 1180mm (W) (will price after looking)	£0.00	£0.00
1	Damaged wall in Locker/bike store area 700mm x 500mm (plasterboard) Prepare and repaint whole wall 6m x 2.3m	£475.00	£475.00
1	repair hole in plasterboard 500mm x 200mm Paint repaired area only	£100.00	£100.00
1	(diagnostic charges only)Air Conditioning Unit: Internal & External Error code showing on control panel. Both internal and external not working due to this issue. External A/C dimensions 9700mm (H) x 9700mm (W).	£200.00	£200.00



Estimated Quote

Hrs/Qty	Service	Rate/Price	Sub Total
1	Cleaners' cupboard: <ul style="list-style-type: none">• Repair holes in plasterboard, prepare and repaint walls, refix mop holder (currently onsite)• Room dimensions 1.2m x 2.4m x 2.4m (H)• $2.88 \times 2 = 5.7 * 2 = 17 = 435$	£600.00	£600.00
2	Supply and install coat hooks on inside toilet doors (1 each in male and female)	£100.00	£200.00
1	Hot water pressure is very low in all sinks on the premises. diagnosis charges	£80.00	£80.00
Sub Total			£1,805.00
Tax			£0.00
Total			£1,805.00

<https://wefix24.co.uk/terms-conditions/>