



Estimated Quote

From:

HandyManSouthampton

Southampton

Contract no.: 07300300155

E: info@wefix24.co.uk

www.wefix24.co.uk

Estimated Quote Number HMS143

Estimated Quote Date 29/03/2023

Valid Until 28/04/2023

Total £2,526.00

To:

Getir po35fl

Hrs/Qty	Service	Rate/Price	Sub Total
1	Electric Shutter: (High Priority) diagnose charges only	£150.00	£150.00
0	Main entrance Door: the door is damaged from in and out top and bottom. door shutting problem. we aim fix the shutting problems	£500.00	£0.00
1	Wall in locker area/ biker store: Damaged wall in Locker/bike store area 700mm x 500mm (plasterboard) Prepare and repaint whole wall 6m x 2.3m	£475.00	£475.00
1	Shop Freezer area: repair hole in plasterboard 1500mm x 3500mm Paint repaired area only. exposed electrical wires behind	£200.00	£200.00
2	Air Conditioning Unit: Internal & External. (diagnosis charges) Error code showing on the control panel. Both internal and external are not working due to this issue. External A/C dimensions 9700mm (H) x 9700mm (W). (diagnostic charges only)	£200.00	£400.00



Estimated Quote

Hrs/Qty	Service	Rate/Price	Sub Total
1	Cleaners' cupboard Repair holes in plasterboard, prepare and repaint walls, refix mop holder (currently onsite) Room dimensions 1.2m x 2.4m x 2.4m (H)	£600.00	£600.00
2	Toilet Coat Hooks: Supply and install coat hooks on inside toilet doors (1 each in male and female)	£100.00	£200.00
0	water pump supplied and fitted if needed	£600.00	£0.00
1	call out fee	£80.00	£80.00
Sub Total			£2,105.00
Tax			£421.00
Total			£2,526.00

<https://wefix24.co.uk/terms-conditions/>